



Note: All the plywood pieces you see were made by the previous owner and are not part of the original LongMill

X, Y & Z connectors from motors to Controller

Drag Chain

Gantry

Z-Axis Lead Screw

Router

Dust shoe/ Vacuum connection

X-Axis rail

X-Axis Lead Screw

Right Y-Axis rail

Y-Axis Lead Screw

USB cable – laptop to controller

Magnetic touch plate

Cable for magnetic touch plate

Power Supply

Extra links for drag chains

Controller/ Electronics

Left Y-Axis rail

Wrenches for router collet

USB connection